Irrigation Repair Schedule

Completion dates are based on good weather days. If bad weather occurs start dates and completion dates may change.

Residence front and back yards:

Controller 9779 Wake Bridge

Address: 9707 to 9959 front and back yards; adjust and replace heads: 2-17-16

Controller 10035 Wake Bridge

Address 9971 to 10091 front and back yards; adjust and replace heads: 2-19-16

Controller 10143 Wake Bridge

Address 10103 to 10199 front and back yards; adjust and replace heads: 2-23-16

Controller 10148 Wake Bridge

Address: 10100 to 10196 front and back yards; adjust and replace heads: 2-23-16

Controller 10092 Wake Bridge

Address 10040 to 10092 front and back yards; adjust and replace heads: 2-24-16

Controller 9842 Wake Bridge

Address: 9842 to 9998 front and back yards; adjust and replace heads: 2-26-16

Controller Crimson Oaks

Address 5315 to 5477 front and back yards; replace valve, adjust and replace heads: 2-29-16

Controller 9912 Fleetwood

Address: 9840 to 9996 front and back yards; adjust and replace heads: 3-2-16

Controller 9913 Fleetwood

Address 9917 to 9997 front and back yards; adjust and replace heads: 3-3-16

Controller 5432 Alderwood

Address 5308 to 5452 front and back yards; replace valve, adjust and replace heads: 3-7-16

Controller 10147 Summit Run

Address 10039 to 10147 front and back yards; replace valve, adjust and replace heads: 3-9-16

Controller 10154 Summit Run

Address 10138 to 10194 front and back yards; replace valve, adjust and replace heads: 3-14-16

Controller 10074 Summit Run

Address 10074 to 10130 front and back yards; adjust and replace heads: 3-16-16

Controller 10091 Summit Run

Address 10091 to 10093 front and back yards; adjust and replace heads: 3-17-16

Controller 10323 Summit Run

Address 10251 to 10359 front and back yards; adjust and replace heads: 3-19-16

Controller 10252 Darkwood

Address 10252 to 10360 front and back yards; replace valve, adjust and replace heads: 3-22-16

Controller 10347 Darkwood

Address 10203 to 10347 front and back yards; replace valve, adjust and replace heads: 3-25-16